

A method for improving moldability of brittle refractory metals such as W, Mo, Cr, and their alloys by doping. Partially soluble metals such as Co, in which martensitic transformation occurs during cooling and/or deformation, are introduced to the molten metal as alloying elements in the amount of 3-6 wt. %.