

A method for control of surface reflectance of alloy with martensitic transformation includes alloy heating to quenching temperature, with soaking during 10-30 minutes, with cooling the alloy to temperatures of interval of direct martensite transformation with obtaining 10-100 % martensite phase.