

Method for treating melts with powder wire comprises of insertion of the powder wire to the depth of the melt, with its dissipation and with achieving refining and modification. Immersing of the powder wire is performed in spiral of Archimedes, through rotating the vessel with metal with simultaneous reciprocal motion of the block with the powder wire out from the center of the vessel with metal, to the periphery.