

Method for obtaining rotted straw is realized through dew-retting, or retting by sprinkling. At that, the strip of the flax straw is treated with composition including urea phosphate, surface-active substance and water.