

Method for formation of fire-explosion safe medium at coal extraction includes fresh air flow supply to the pit-face of extraction site and discharge of worked-out air from the pit-face of the extraction site. To the flow of fresh air one adds nitrogen in amount not less than 98.5 % in total volume of the fresh air flow.