

Footwear with a measuring balance has blanks of upper, insole and sole and a pocket balance, which have the body with a loading platform, wherein piezoelectric elements, the electrodes of which are connected with transistor exciters and an indicator, are arranged. The footwear has in soles hollows (grooves) to which the elastic containers filled by a nonfreezing liquid or air and connected to each other by connecting tubes are inserted. On one of the blanks of footwear a measuring scale or a manometer connected to elastic containers by the central flexible hose is fixed. The measuring scale or manometer is equipped with the back valve.