

The method for monocrystal growing by Czochralski technique with a control of resistance of nucleus-melt area, wherein a resistance is controlled till the stage of mechanical contact of a nucleus with melting surface, a resistance is controlled at different polarity of a tension, applied to a nucleus relatively to a melt, and value of this resistance is a criterion of distance between a nucleus and melting surface.