

In the method for operation of getting machine along breakage face in mining face one measures gas concentration and depending on result of measurement one generates warning signal. At that in addition one determines volume of coal produced and in case of insufficient correlation between volume of coal produced and gas concentration one generates warning signal.