

A method for manufacture of decorative articles involves molding, coloring, drying of article. First, unsaturated polyester resin is heated to the temperature of 40-50 °C, catalyst for accelerating the reaction is added, then is added the chalk as a filler and mortar sand.