

Method for torch shooting of melting facility includes delivery to lining distributed jets of fireproof powder, fuel and oxygen. The shooting is carried out after oxygen blowing the melt up to the carbon content not more than 2.5 %, and then the blowing is made up to the necessary carbon content.