

A finishing method of ceramic tile comprises the stages of engobe coating, glazing, tile drying, burning and paint impressing by stencil method with a further drying of semiproduct. For the impressing the paint of UV-solidification is used. The drying stage of the semiproduct is carried out with the help of UV-lamps.