

A method for measuring human foot includes putting the foot on a support surface of measuring device and obtaining foot impression on paper. A scanner is used as measuring device. Each foot is alternately put on the upper support surface in parallel to the support, than scanning is performed. Prior to obtaining the impression on paper an image of planetary foot surface is transferred on the computer display using Microsoft Office Word.