

A method for ignition and sintering of agglomerated mixture includes ignition of the charge, the use of air enriched with oxygen, for 20-60 % of the sintering time, since the output of the charge from the ignition furnace. A part of the solid fuel in the amount of 5-20 % of the total quantity of solid fuel in the charge is applied to the surface layer of the charge.