

The method of creation of crystal image on the surface of the material includes: surface preparation phase crystals and the surface material and the stage of formation crystal image. Stage crystals surface preparation and surface material includes adhesive layer crystals, completing crystal set, drawing symbols on material contour imaging and \ or form a separate element of the image, which is applied to the front side of the material using computer software / or specialist adhesive layer on the front surface of the material, assembly algorithm identification symbols on the surface of the material symbols of crystals set the size and color of each crystals. Phase imaging includes attaching rhinestones with crystal set on the front side of the material according to the algorithm identification symbols, glue method. Attach rhinestones on each symbol, carry only matches the size and color of crystals set and the size and color of a symbol on the surface of the material. The following material is used for crystal image: fabric, leather or artificial counterparts.