

A method for measuring resistance pressure value when comminuting meat raw material consists in that measured minced meat resistance pressure value in meat grinder plate is converted to electric signal by means of strain gage transducer. The electric signal from strain gage transducer is transmitted by means of amplifier to analog-to-digital converter and as digital signal is graphically displayed on personal computer monitor by means of software.