

The press of dry pressing contains the crankshaft mounted on the frame, the connecting-rod and pressing lever hinged with the connecting-rod with the help of a pin. To provide stabilization of pressing effort the pin is mounted with possibility of rotation with respect to the connecting-rod and pressing lever. The surface of pin that is connected with the connecting-rod is eccentric with respect to the surfaces that are connecting with the pressing lever. The pin is equipped with additional lever. The movable support is connected with the frame in such a manner that it cooperates with additional lever.