

A preventive-unloading device of rolling mill has a puncheon placed under a screwdow structure, belt and foundation, formative the working cavity filled by high-plastic material, and the destroyed unite. A belt is made as two hard semirings connected between itself on one end by a hinge, and on other - the destroyed unite made as a cut away finger, and elastomer is used as a high-plastic material.