

The tap contains boarding, calibrating and end parts. The angle of raising the thread on each tooth is less than the nominal angle of raising the threads for the value from $2^{\circ}30'$ to the value of the angle of relieving of lateral side of tooth.