

The method for preparation of oxidized coal comprises thermal treatment of activated carbonic material by wet air. Temperature treatment process should be carried out at the temperature of 390-470°C during 1- 12 hours. The invention relates to the methods for production of carbonic sorbents and may be used at production of sorbents-ion-exhcangers and catalysts on the basis of oxidized carbons.