

Drill workbench support has two semi-rings, forming a guide bushing installed in a ring. The ring rests on amortization circular elements mounted in the body. To exclude supplementary operations on disassembling and assembling in order to put through the beams stabilizers the guide bushing surface has long slots, and its upper end is arranged as multi-entrance screw surfaces. At that, the lower end of the bushing rests on a spring-supported circular element installed in the ring with possibility of limited displacement in axial direction.