

The proposed method for starting an asynchronous motor that is powered from a three-phase inductive-capacitive converter with additional windings consists in connecting the motor, for the start period, to the mains via the additional windings of the converters.