

A shaped-charge warhead includes hollow charge, blaster fuse, safety-executive mechanism, detonator. To get over armored protection of modern tank one uses lined hollow charge as a hollow charge that is placed throughout the length of rocket in parallel to long axis of the rocket. Direction of hitting of the lined hollow charge is deflected from long axis downwards by 90 degrees. Noncontact fuse is included, this is connected to safety-executive mechanism and detonator.