

Method for passive protection of hermetic shell of reactor compartment against exceeding rated pressure includes condensation of vapor in hermetic volume, jet-drop cooling of vapor-air mix with cooling solution, supply of cooling solution with injector, de-cooling of hermetic volume, heat rejection.