

The process of treating the fibrous material comprises treatment of material with hydrogen peroxide at room temperature in an acidic buffer solution in presence of an iron (II) salt catalyst.