

Method download bed on the grate sinter machine conveyor includes a separation charge by size into two fractions, - b and certified the charge with the help of inclined belt conveyor with variable angle of inclination with the subsequent transfer of selected fractions of the material bed on the grate, and the standard charge - layer on top of the bed. The charge is lumped and after download crumpled isolated from the charge material bed on the grate of a sinter machine to measure the actual height of the bed, compare the measurement results with a specified value.