

A process for the preparation of walnut kernel concentrate and oil involves cold extrusion with simultaneous preparation of oil and concentrate. A modified electric oil press is used as processing equipment. Cold oil extraction is performed at a temperature below 50 °C, and walnut kernels are used.